

ASBESTOS

(Floor Tile & Mastic Removal)

POSSIBLE AREAS OF CONCERN

Asbestos-containing floor tile is common on Fort Campbell. The glue (mastic) that holds the tile in place may also contain asbestos.

CHARACTERIZATION


Asbestos-containing materials are managed as a Special Waste.

HANDLING PROCEDURES

- Step 1** Review the Building Occupant Notification Form (BONF) or contact **DPW Work Management Branch** or **Environmental Division TSCA** to determine if floor tile is asbestos containing.

- Step 2** If the floor tile has become loose from the floor, place in a plastic bag and call the **DPW Asbestos Maint. Team** for pickup.

- Step 3** If the floor tile has become deteriorated, damaged or otherwise in poor condition, unit FMT should submit Work Order to **DPW Service Order Section** or call **DPW Service Orders** to submit a service request for removal/replacement of asbestos containing material.



Always refer to your BONF before beginning work

NOTE: Activities such as sanding or grinding, drilling, or sawing of asbestos containing floor tile **SHALL NOT** be allowed. Further, Self-Help removal of asbestos-containing tiles is prohibited.

GENERAL INFORMATION

For additional information, see protocol sheet A-11 or contact **Environmental Division TSCA**